

# LABORATORY TEST REPORT

[www.protechpowder.com](http://www.protechpowder.com)



**Customer:** Fort Mill Ornamental  
**Date:** 2/22/2019  
**Project:** 100276 / CLE02218  
**Product:** ZS311N107, Z series, Super Durable  
**Material Standard:** AAMA 2604-05

**Evaluation:** 7.8.2 Salt Spray Resistance  
**Test Methods:** ASTM B117, Salt Spray Cabinet Conditions  
ASTM D1654, Scribe & blister rating  
**Specimens:** 4 Parts (aluminum fencing pieces)  
Parts were cleaned and pretreated with Calvary Chemical's Zirconium.  
**Exposure:** 3000 Hrs. - Remove & wipe sample dry and Immediately apply tape (Permacel 99 or equivalent).  
**Test Chamber:** Singleton 22  
**Scribed Lines:** One Straight Line  
**Scribing Tool:** Straight Shank, Tungsten Carbide Tip  
**Examinations:** Measure and rate creepage from scribe plus rate appearance of unscribed area  
**Requirements:** Minimum rating of 7 on scribe or cut edges, and a minimum blister rating of 8 within the test specimen field, accordance with Table 1 and 2 (Reference ASTM D1654).

Representative Mean Creepage From Scribe		
Millimeters	Inches (Approx.)	Rating Number
Zero	0	10
Over 0 to 0.5	0 to 1/64	9
Over 0.5 to 1.0	1/64 to 1/32	8
Over 1.0 to 2.0	1/32 to 1/16	7
Over 2.0 to 3.0	1/16 to 1/8	6
Over 3.0 to 5.0	1/8 to 3/16	5
Over 5.0 to 7.0	3/16 to 1/4	4
Over 7.0 to 10.0	1/4 to 3/8	3
Over 10.0 to 13.0	3/8 to 1/2	2
Over 13.0 to 16.0	1/2 to 5/8	1
Over 16.0	Over 5/8	0

TABLE 1: Rating of Failure at Scribe (Procedure A)

Area Failed, %	Rating Number
No Failure	10
0 to 1	9
2 to 3	8
4 to 6	7
7 to 10	6
11 to 20	5
21 to 30	4
31 to 40	3
41 to 55	2
56 to 75	1
Over 75	0

TABLE 2: Rating of Unscribed Areas (Procedure B)

**Results:**

Panel ID	Creepage Form Scribe in mm		Blistering	
	Mean	Rating No.	Area Failed, %	Rating No.
1	0	10	No Failure	10
2	<0.5	9	>3%?	8
3	0	10	<3%	8
4	<0.5	9	<1%	9

**Conclusions:** Parts 1 and 4 both passed for scribe creepage and blistering in the test specimen field. Parts 2 and 3 both passed for scribe creepage and blistering in the test specimen field. The bottom area of Parts 2 and 3 produced a very blistered appearance. This contamination is most probably due to the observed handling of the parts prior to coating and is not representative of the pretreatment or substrate.

# LABORATORY TEST REPORT


[www.protechpowder.com](http://www.protechpowder.com)



# LABORATORY TEST REPORT

[www.protechpowder.com](http://www.protechpowder.com)

## Panel ID # 2





# LABORATORY TEST REPORT

[www.protechpowder.com](http://www.protechpowder.com)



# LABORATORY TEST REPORT

[www.protechpowder.com](http://www.protechpowder.com)

